



DIGITAL MOISTURE METER




TECHNICAL PARAMETER

- > Scope of moisture measurement: 6 ÷ 40%
- > Resolution: 0,1%
- > Operating Temperature: 0 ÷ 40 °C
- > Storage Temperature: -10 ÷ 50 °C
- > Influence of humidity: ≤ 80%
- > Power supply: 1pc 6F22 9V battery

OPERATIONAL DESCRIPTION

1. Install Battery
2. Take off the protective cover of the probe, and switch the instrument ON by pressing ON/OFF botton. Insert the detecting head of the meter about 5 mm into measured object.
3. Then the testing value displayed on the screen is the water content of the object.

ATTENTIONS

1. The detecting head of the meter is very sharp, so keep ita way from children or do not let children play with it to prevent injury.
2. Do not aim the detecting head for measurement towards any person or animal to avoid injury.
3. The metere is not allowed to be used to measure any charged object lest the meter might be damaged
4. When the sign  is displayed on the screen, it indicates that the battery voltage is low. To ensure the accuracy of the measurement, please replace it with a new 9V battery of the same type
5. In the event that the meter is left unused for a long time, take out the battery so as to avoid the damage of the meter due to leakage or other reasons.
6. The meter is hygh resistance instrument, so various part shall be kept in insulater, moisure free and dust proof storage areas and the maeter shalll be kept clean and dry to ensure the accuracy of the measurement and the service ability of the meter.